

Ben Sticka
November 27, 2019
Page 3 of 3

Landmark Tree T86

As discussed above, there are 16 landmark trees on project Site. Landmark tree T86 is located within 8-feet of the proposed internal right-of-way. Due to no future connection potential, in order to develop the site to its reasonable development, the internal road had to be centrally located. Also, the removal of this tree is already included within the proposed 35% retention rate for the entire site.

Thank you for reviewing this landmark tree removal exception request. If you have any questions or concerns regarding the information, please do not hesitate to contact me.

Sincerely yours,

D. R. STRONG Consulting Engineers Inc.

A handwritten signature in black ink, appearing to read "Yoshio Piediscalzi". The signature is written in a cursive, flowing style.

Yoshio L. Piediscalzi, P.E.

Director of Engineering

YLP/lcs